Palm Mitigation Schedule

Palm ID#	Palm Type	Caliper	Northing	Easting	Action	Remarks
281	PALM	10.000	741956.3100	931202.9900	Remove	
282	PALM	10.000	741963.9400	931204.2500	Remove	
283	PALM	12.000	742243.9300	931206.3800	Remove	
284	OAK	20.000	741990.0100	931209.1200	Remove	
285	PALM	9.000	742308.8600	931210.4700	Remove	
286	PALM	6.000	742292.6500	931211.7400	Remove	
287	PALM	14.000	742238.5200	931211.9300	Remove	
289	PALM	10.000	741980.1800	931214.8300	Remove	
290	PALM	15.000	742514.1200	931216.1200	Remove	
291	OAK	16.000	742062.5300	931219.0500	Remain	
292	PALM	16.000	742328.5900	931219.2800	Remove	
383		0.000	741842.2974	931220.1250	Remove	
293	PALM	8.000	741981.0300	931222.9200	Remove	
294	OAK	20.000	742211.3800	931225.9300	Relocate	
295	OAK	24.000	742232.7900	931227.4900	Relocate	
296	PALM	18.000	742325.8000	931236.7200	Remove	
297	OAK	12.000	742426.5200	931237.1000	Remove	
384		0.000	741881.5480	931239.9196	Remain	
298	PALM	6.000	742522.6400	931248.5400	Remove	6" X 2 PALM CLST
299	PALM	9.000	742605.7400	931250.0900	Remain	
300	OAK	10.000	742482.3100	931252.2000	Remove	
301	PALM	10.000	742592.3100	931255.1400	Remain	
302	PALM	11.000	742602.0600	931256.2300	Remain	
303	OAK	8.000	742422.8500	931256.8100	Remove	
304	PALM	8.000	742596.8900	931260.2000	Remain	8" X 3 PALM CLST
305	PALM	10.000	742610.8200	931260.2900	Remain	
306	PALM	11.000	742625.5000	931262.0300	Remain	
307	PALM	9.000	742584.7200	931266.1700	Remain	
308	OAK	18.000	742160.3600	931268.0200	Remove	
309	PALM	9.000	742618.5500	931268.1300	Remain	
310	PALM	16.000	742523.6700	931268.9000	Remove	
311	PALM	7.000	742576.4300	931271.2200	Remain	
312	OAK	13.000	742477.4700	931271.7300	Remove	
382		0.000	741876.8032	931271.7946	Remove	
313	PALM	10.000	742626.4300	931276.5400	Remain	
314	PALM	6.000	742572.3100	931276.7100	Remain	
315	PALM	6.000	742562.9400	931278.0000	Remain	
316	PALM	7.000	742568.3900	931278.8100	Remain	
317	PALM	8.000	742559.1500	931280.3200	Remain	
374		0.000	741990.4957	931280.8681	Remove	
318	PALM	7.000	742554.2600	931282.2400	Remain	
371		0.000	741983.2395	931282.8473	Remove	
319	OAK	16.000	742325.4700	931283.1600	Remove	
320	PALM	10.000	742650.0600	931283.3600	Remain	
373		0.000	741991.6501	931288.9506	Remove	
372		0.000	741983.4042	931289.9405	Remove	
321	OAK	12.000	742509.5500	931291.1700	Remove	
322	PALM	12.000	742636.5600	931292.7800	Remain	
323	PALM	14.000	742607.8900	931298.0500	Remain	
348		0.000	742399.1770	931299.6856	Remain	
369		0.000	741946.1241	931300.1689	Remove	
324	PALM	6.000	742323.6100	931300.2500	Remove	
346		0.000	742365.5334	931302.3247	Remove	
366		0.000	742103.2249	931302.6477	Remove	
379		0.000	741907.4781	931303.3013	Remove	
368		0.000	742041.8402	931303.3059	Remove	
350		0.000	742394.7240	931305.2939	Remove	
349		0.000	742400.3314	931305.2939	Remove	
381		0.000	741861.6304	931305.6105	Remove	
364		0.000	742153.9090	931306.2791	Remove	
351		0.000	742398.1873	931309.4179	Remove	
363		0.000	742207.0836	931310.0761	Remove	
352		0.000	742390.1064	931311.2327	Remove	
353		0.000	742385.9833	931313.8719	Remove	
376		0.000	741989.0115	931315.0140	Remove	

Palm Mitigation Schedule

Palm ID#	Palm Type	Caliper	Northing	Easting	Action	Remarks
325	OAK	12.000	742593.5700	931316.4200	Remove	
360		0.000	742249.6788	931316.5151	Remove	
326	BANYAN	108.000	742309.9400	931317.1100	Remove	
347		0.000	742361.7404	931318.4903	Remove	
378		0.000	741954.3786	931318.6425	Remove	
354		0.000	742384.6642	931318.8202	Remove	
365		0.000	742127.8522	931318.9806	Remove	
367		0.000	742080.7605	931319.1415	Remove	
377		0.000	741994.9486	931319.3024	Remove	
362		0.000	742177.7283	931320.4683	Remove	
375		0.000	741984.8888	931321.2822	Remove	
355		0.000	742393.2399	931321.4594	Remove	
370		0.000	741922.4802	931324.4204	Remove	
343		0.000	742415.0677	931325.1065	Remove	
361		0.000	742231.3270	931326.2416	Remove	
380		0.000	741883.3999	931326.7249	Remove	
327	OAK	6.000	742487.7000	931326.7600	Remove	
359		0.000	742271.9431	931329.5465	Remove	
356		0.000	742385.1586	931332.8415	Remove	
344		0.000	742407.1132	931335.6503	Remove	
357		0.000	742381.0359	931337.6255	Remove	
345		0.000	742356.9577	931338.4498	Remove	
358		0.000	742384.9940	931344.7180	Remove	
328	OAK	15.000	742528.3600	931348.8400	Remove	
330		0.000	742653.9861	931349.2270	Remain	
340		0.000	742462.3991	931351.3342	Remove	
329	OAK	7.000	742555.3200	931353.7900	Remove	
342		0.000	742426.4471	931367.0054	Remove	
338		0.000	742543.9262	931367.1797	Remove	
331		0.000	742640.0036	931382.8496	Remain	
337		0.000	742562.7268	931384.5001	Remove	
341		0.000	742486.9722	931387.6243	Remove	
334		0.000	742637.8389	931391.6130	Remain	
332		0.000	742610.9366	931394.2934	Remove	
339		0.000	742528.0939	931397.3665	Remove	
333		0.000	742634.2315	931405.7371	Remove	
335		0.000	742575.1582	931421.1358	Remove	
336		0.000	742608.1419	931437.7962	Remove	

To the best of the architect's or engineer's knowledge, the plans and specifications comply with the applicable minimum building codes and the applicable fire-safety standards as determined by the local authority in accordance with this section and Chapter 553, Florida Statutes.

REVISIONS

SEAL

© Garcia Stromberg

edsa
1512 E. BROWARD BOULEVARD, SUITE 110
FORT LAUDERDALE, FLORIDA 33301 USA
TEL 954.882.1909
www.edsaplan.com
PLANNING LANDSCAPE ARCHITECTURE URBAN DESIGN

GARCIASTROMBERG
GS4studios
Jorge R. Garcia, RA, NCARB
Owner/Executive Director
AR0017769
Peter T. Stromberg, RA, NCARB
Principal
AR0019893
2965 Vista Parkway, Suite 16, West Palm Beach, FL 33411 TEL 561.478.8855 FAX 561.478.8865
Corporate License # AA26000342

CLIENT - OWNER
BOCA WEST COUNTRY CLUB
Mr. Matthew Linderman
20583 BOCA WEST DRIVE
BOCA RATON, FL 33434

PROJECT INFORMATION
BOCA WEST COUNTRY CLUB
POOL AREA AND PORTE COCHERE
20583 BOCA WEST DRIVE
BOCA RATON, FL 33434

DRAWING SHEET NAME
TREE DISPOSITION SCHEDULE
L1-0-02

PROJECT # 19000
SHEET #

100% DESIGN DEVELOPMENT - ISSUED FOR BID
PLOT DATE: JANUARY 15, 2021
PRINT DATE: JANUARY 15, 2021